1	Appl. No. 10/748,618 Amdt. dated Dec. 5, 2005 Reply to Office action of Jan. 2006 Regarding Missing Signature position as well as versus angle is now described in Claim 24, as depicted in Fig. 14A-D,
2	while a similar system having optical systems disposed within the distances between source
3	array and first optical and first and second optical sheet is described in Claim 27 so as to
4	provide a top-hat uniformity profile across position at a first illumination plane as well as
5	across position and versus angle at a second illumination plane, as depicted in Fig. 3.
6	The new claims 20-28 are intended to better describe the illumination system cases as
7	stated than the previous Claims 14, 15, and 17.
8	3. Amendments to Drawings:
9	In amended Figure 16A, the previously omitted element numeral 150 has been added.
10	In Fig. 1-3, Fig. 7D-7F, Fig. 9A-9H, Fig. 10A-10F, Fig. 11A-11D, Fig. 12C, Fig. 14C
11	Fig. 16A, Fig. 16D, Fig. 17A-17B, and Fig. 18-19, erroneous lines in the illustrations have
12	been corrected. Upon review, these errors were found to be caused by printer errors and have
13	now been corrected. Previously used reference words used in Figures 21, 22, and 23 have
14	been replaced with numerical reference signs. Extra words in Figures 17 and 18 have been
15	removed.
16	
۱7	Respectfully submitted,
18	KARLTON D. POWELL
19	Karlton D. Powell
20	Karlton D. Powell
21	Tel.: (425) 220-1291